

03500.016185



PATENT

cofe \$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
KAZUMI KIMURA) Examiner: A. Do
Application No.: 10/073,108) Group Art Unit: 2624
Filed: February 12, 2002)
For: SCANNING OPTICAL APPARATUS)
AND IMAGE FORMING APPARATUS)
USING THE SAME)
U.S. Patent No.: 7,039,257)
Issued: May 2, 2006) October 20, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

*Certificate
OCT 26 2006
of Correction*

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/25/2006 AWONDAF1 00000051 7039257


01 FC:1811

100.00 OP

OCT 26 2006

Patentee's undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Michael K. O'Neill
Attorney for Patentee
Michael K. O'Neill
Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 122147v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,257

DATED : May 2, 2006

INVENTOR(S) : Kazumi Kimura

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 39, "resulting" should read --resulting in--;

Line 55, "surfaces" should read --surfaces--.

COLUMN 10

Line 66, "manufacture" should read --manufactured--.

COLUMN 11

Line 26, "clockwisely" should read --clockwise--.

COLUMN 13

Line 3, "effecting" should read --effective--;

Line 21, "light" should read --a light--;

Line 37, "incident" should read --an incident--;

Line 38, "in scanned" should read --is scanned--.

COLUMN 14

Line 2, "light" should read --a light--

Line 20, "incident" should read --an incident--; and

Line 1, "in scanned" should read --is scanned--.

MAILING ADDRESS OF SENDER:

PATENT NO. 7,039,257

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)
CA_MAIN 122148 v1

→ _____
OCT 26 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,039,257

DATED : May 2, 2006

INVENTOR(S) : Kazumi Kimura

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 39, "resulting" should read --resulting in--;

Line 55, "surfaces" should read --surfaces--.

COLUMN 10

Line 66, "manufacture" should read --manufactured--.

COLUMN 11

Line 26, "clockwisely" should read --clockwise--.

COLUMN 13

Line 3, "effecting" should read --effective--;

Line 21, "light" should read --a light--;

Line 37, "incident" should read --an incident--;

Line 38, "in scanned" should read --is scanned--.

COLUMN 14

Line 2, "light" should read --a light--

Line 20, "incident" should read --an incident--; and

Line 1, "in scanned" should read --is scanned--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,039,257

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)
CA_MAIN 122148 v1

→ _____

OCT 26 2006